| A. REQUEST FOR OFFERS (THIS IS NOT AN ORDER) | | | 1. REQUEST NO. DTFAAC-09-Q-06122 | | | | PAGE | |
|--|--|--------------------------|--|---|-------------------|---------------|------------------------|---|
| 2. DATE ISSUED: | | | 3. REQUISITION/PURCHASE REQUEST NO.: | | | | | |
| 4a. ISSUED BY: FEDERAL AVIATION ADMINISTRATION NAS Automation & Facilities Acquisition Division (AMQ-210) 6500 South MacArthur Boulevard P.O. Box 25082 Oklahoma City, OK 73125-4931 | | | | AC-09-06122 5. DELIVERY BY 15 DAYS ARO - | | | X_F | IVERY: OB DESTINATION OTHER |
| | MATION CALL: (NO COLLECT CALLS) s: mary.skaggs@faa.gc | | H:405-9 | 954-7816 F | 'AX: 405-9 | 954-9219 |) | |
| Contractor shall propose in accordance with this request as well Statement of Work that follows. | | | I as the | | | | | |
| | RNISH OFFER TO THE ISSUING O | | 10. BUSI | NESS CLASSIFIC | CATION (CHECK A | LL THAT APPLY | 7 | |
| | | | MALL DISADVANTAGED THER THAN SMALL WOMEN OWNED | | | | | |
| This request do services. Supp | This is a request for information, an bes not commit the Government to olles are of domestic origin unless eted by the offerer. | pay any costs | incurred in | the preparations | of the submission | on of this qu | otation or to | contract for supplies or |
| | | | | EDERAL, STATE, AND | ., . | 1 | T | |
| | n reporting requirement of 26 U. tification Number is required. T | IN: | 41A and i | | | | UNIT PF ernal Rever | |
| в. | SUPPLIES/SERVICES AN | D PRICES/ | COSTS | | Quantity | Unit | Unit Price | Line Amount |
| 0001 | MPS1000 16 Channel Communication Server | | | | 66 | EA | \$ | \$ |
| 0002 | MPS1000 8 Channel Communication Server | | | | 15 | EA | \$ | \$ |
| 0003 | 4XEIA530 Hydra Cable | | | | 207 | EA | \$ | \$ |
| 0004 | RS232 Debug Cable | | | | 81 | EA | \$ | \$ |
| 0005 | Right to Use Software Custom Bundle | | | | 81 | EA | \$ | \$ |
| 1 | | | | | | | | |
| 12. DISCOU | NT FOR PROMPT PAYMENT | 10 CALENDA | R DAYS % | 20 CALENDAR | DAYS 30 CAL | ENDAR DAY | s(| CALENDAR DAYS % |
| 13. NAME AND | ADDRESS OF OFFERER (STREET, CT CODE) | TY, COUNTY, STATE AI | | 14. SIGNATUR TO SIGN C | RE OF PERSON | AUTHORIZI | | 5. DATE OF OFFER |
| | | | | 16. NAME AND | TITLE OF SIGN | ER (TYPE OR I | PRINT 15 | 7. TELEPHONE NO. (INCLUDE AREA CODE) |

STATEMENT OF WORK

Integrated Terminal Weather System (ITWS)
MPS1000 Procurement

AJW-14A 08 Jul 2009

TABLE OF CONTENTS

| 1.0 | Background |
|-----|---------------------------------|
| 2.0 | Scope |
| 3.0 | Contractor Tasking/Requirements |
| 4.0 | Warranty |
| 5.0 | Schedule |
| 6.0 | Deliverables |

1.0 BACKGROUND

This Statement of Work (SOW) is for the purchase of new and like item parts for the Integrated Terminal Weather System (ITWS), which is installed at 27 TRACONs, with 6 more to be installed by the end of 2009. This effort is termed "MSP1000 Procurement". The ITWS provides Air Traffic Controllers with real-time weather products including Microburst and Windshear alerts and alarms, for use in the Terminal area of operations. The ITWS is required for safety and efficiency of the NAS at these airports.

The MPS1000 is a Commercial Off the Shelf (COTS) piece of equipment in the ITWS rack that accepts input weather data from many weather sources, including the ASR9 radar, ASR11 radar, NEXRAD radar, TDWR radar, and the National Weather Service (NWS). The ITWS was acquired by the FAA program office from Raytheon, beginning in 1998. The first twenty-two (22) ITWS racks (of the thirty-three total) were deployed by Raytheon with the Performance Technologies MPS800 Communications (Comms) Concentrator. The ITWS software was developed to communicate with and control the Performance Technologies MPS800 device, to facilitate communications with various radars such as the ASR9, ASR11, and NEXRAD. The MPS800 model became End of Life (EOL) in 2007, and it is no longer supported by the manufacturer. In addition, replacement units are no longer available when these units fail. Therefore, the FAA directed the ITWS contractor (Raytheon) to deploy the last eleven (11) ITWS sites with the newer version of the comms concentrator, the MPS1000. AJW-14A was funded by the ITWS Program Office to retro-fit the first twenty-two (22) ITWS sites with the new Performance Technologies MPS1000. This retrofit is required to ensure that the fielded ITWS equipment is fully supportable and maintainable.

2.0 SCOPE

The Contractor shall provide all material, labor, transportation, freight, etc. necessary to deliver to the MMAC in Oklahoma City items needed to retro-fit 22 ITWS sites as described in Paragraph 1.0 above. the five COTS items listed in section 3.1 below, to the PSF, AJW-14A.

3.0 CONTRACTOR TASKING/REQUIREMENTS

3.1

3.1.1 The following five (5) items shall be delivered to the following address:

6500 S. McArthur Blvd Building 196 Oklahoma City, OK, 73169

| LINE ITEM | DESCRIPTION | QTY | PART NUMBER | DELIVER BY |
|-----------|--------------------------|-----|------------------|-------------|
| 0001 | MPS1000 16 Channel Comms | 66 | PT-MPS1000-12053 | 30 Days ARO |
| 0002 | MPS1000 8 Channel Comms | 15 | PT-MPS1000-12159 | 30 Days ARO |
| 0003 | EIA530 Hydra Cable | 207 | PT-ACC334-12273 | 30 Days ARO |
| 0004 | RS232 Debug Cable | 81 | PT-ACC358-12275 | 30 Days ARO |
| 0005 | Software bundle | 81 | PT-WANRTU-91332 | 30 Days ARO |

3.1.2 The F.O.B. point for this effort is Destination.

4.0 WARRANTY

The contractor shall provide a warranty identical to the standard commercial warranty for line items listed in paragraph 3.0. Generally, such a warranty is one year from the time of final Government acceptance.

5.0 SCHEDULE

The contractor shall deliver the items listed in paragraph 3.0 within 30 days After Receipt of Order (ARO).